

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representation of
The original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

EXHIBIT A

MAGNA

To: JACQ. BARUEKA

3-8% by Volume
maybe more (max 20%)

viscosity not a much
of a problem w/ blow holding
not trying to flow material
low pressure blowing rather
than flowing.

20% may be really strong
for really high strength
applications - Intrusion Beams
- Seat Belts
- Load Floors


5 pieces total


Dr. Phillip S. Wilson


Modulus Here 500K

Resin



INTEGRAL BLOW-MOLDED
BUMPER, RADIATOR &
LIGHTING SUPPORT
STRUCTURE







BLOW-MOLDED
BUMPER HAVE
CAVITIES THAT
CONTAIN ANTI-FREEZE
& WASHER FLUIDS



WINDSHIELD
WASHER FLUID
RESERVOIR

ANTI-FREEZE
RESERVOIR

FILTER
DOORS

① Eliminate Parts

② Absorb some energy in
pushing fluid around
Blow molded unreinforced bumpers
do exist